## **AnnexureD**

## BUILDINGSAFETYCERTIFICATE

		-	1.			
No.	XIL	C	12	48/	2	5

Dated: 16/7/25

It is certified that the existing building New Divine Public School...(name of the building or premises) at

Vill - Behranpur, Kharkhoda, Meerut (address)is having block(s)/Floor(s)as per details below:

Detail of Block(s)in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No.of Floor(s) in the						
Block	G + 1	NA	NA	NA	NA	NA

The building is owned/ occupied by New Divine Public School (name

of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Rular Engineering Services, ViII – Behranpur, Kharkhoda, Meerut (Name of Department/Govt.)on. 15/2/25...(date of inspection)in the presence of Mr. Jagdish, ViII – Behranpur, Kharkhoda, Meerut (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from. 16/7/25...for a period of 3years in accordance with rule and subject to compliance of the specific conditions as appended.

1.			
2.	NA		
3.	10 /1		
4.	1 - 1	0 .	
Issuedon16	/7/25 at	PWd,	Meerutby

प्राचीन बानव का नि

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet fordetail.

Signature with Seal :	
Name :	
Designation :	
Name &Address of Department/Office:	